

**Amendments and clarification to Code of Practice
for Fire Resisting Construction 1996**

I refer to the recent issue of the revised Code of Practice for Fire Resisting Construction 1996 which shall be effective on 1 August 1996. The following corrigenda therein are required:-

- (i) On page 9, in the fourth line of paragraph 7.2, "but in no case less than 2 hours" should be deleted.
- (ii) On page 18, at the end of paragraph 17.2, the following diagram should be added :

**FIRE DOOR
TO BE KEPT CLOSED**

防火門
應常關

- (iii) In Table C on page 24, the concrete cover to all reinforcement required to provide 2 hrs. FRP to continuous floors and landings should read "25 mm" instead of "40 mm".

2. The corrigenda announced in this practice note will be incorporated in future editions of the Code of Practice.



(CHOI Yn-leuk)
Building Authority

Ref. : BD GP/BREG/C/19/L (VII)
PNAP 163

First issued August 1996 (AD/LM)

Index under : Fire resisting Construction, Code of Practice for