

25 Aug 2015

To: All Authorized Persons
Registered Structural Engineers
Registered Geotechnical Engineers
Registered Inspectors
Registered General Building Contractors
Registered Specialist Contractors
Registered Minor Works Contractors

Dear Sir / Madam,

**Technical Guidelines on Minor Works Control System
Addendum (1/2015) on Section 3 Categorisation of Minor Works
Quality control and supervision of Tempered Glass
Repair of Structural Elements
Supporting Structure for Antenna and Transceiver or Radio Base Station on Roof**

The Buildings Department has provided new guidelines for the items listed below in the Addendum (1/2015) on Section 3 Categorisation of Minor Works, which is added to the Technical Guidelines on Minor Works Control System.

1. Quality control and supervision of tempered glass
2. Repair of structural elements
3. Supporting structure for antenna and transceiver or radio base station on roof

This new addendum is uploaded to the website of Buildings Department (www.bd.gov.hk) for your reference.

Yours faithfully,



(LEUNG Siu-man)
Assistant Director / Corporate Services
for Building Authority