





**Diagram 2**

**Minimum clear width of  
the internal corridor serving the “subdivided units”**  
(Fire rated door at the original entrance of the flat is removed or  
replaced by a door not meeting the required fire resistance rating)



**Legend :**

-  The walls separating the “subdivided units” from each other and the walls at both sides of the internal corridor should have a fire resistance rating of **not less than 1 hour**.
-  The door of each “subdivided unit” should be self-closing, smoke sealed and have a fire resistance rating of **not less than 1 hour**.
-  The flat as shown on the original approved plan

All the building works are required to meet the requirements of the relevant building regulations and the Code of Practice for Fire Safety in Buildings.