

Hong Kong

District	Consultant	Contact No.
Central and Western	Easy Living Consultant Limited	2625 0498
	IPS Consultants Limited	3588 1752
	Geotechnics & Concrete Engineering (H.K.) Ltd.	2365 9123
Eastern	Prudential Surveyors International Limited	2507 8333
	Geotechnics & Concrete Engineering (H.K.) Ltd.	2365 9123
	Modern Testing Consultants Ltd.	3171 6823
	Easy Living Consultant Limited	2625 0498
	IPS Consultants Limited	3588 1752
Southern	Fruit Design & Build Limited	3188 5595
	Prudential Surveyors International Limited	2507 8333
	Multiple Surveyors Limited	3966 6766
	IPS Consultants Limited	3588 1752
	Geotechnics & Concrete Engineering (H.K.) Ltd.	2365 9123
Wanchai	Easy Living Consultant Limited	2625 0498
	IPS Consultants Limited	3588 1752
	Geotechnics & Concrete Engineering (H.K.) Ltd.	2365 9123
Island	Fruit Design & Build Limited	3188 5595
	Prudential Surveyors International Limited	2507 8333
	Multiple Surveyors Limited	3966 6766

Kowloon

District	Consultant	Contact No.
Kowloon City	Modern Testing Consultants Ltd.	3171 6823
	P2H Design Associates Ltd.	2866 3688
Kwun Tong	P2H Design Associates Ltd.	2866 3688
	Prudential Surveyors International Limited	2507 8333
	Pioneer Management Limited	2146 8484
	IPS Consultants Limited	3588 1752
	Geotechnics & Concrete Engineering (H.K.) Ltd.	2365 9123
Sham Shui Po	Modern Testing Consultants Ltd.	3171 6823
	Prudential Surveyors International Limited	2507 8333
	Building Diagnostic Consultants Limited	2429 8622
Wong Tai Sin	Multiple Surveyors Limited	3966 6766
	Easy Living Consultant Limited	2625 0498

	Building Diagnostic Consultants Limited	2429 8622
Yau Tsim and Mongkok	Modern Testing Consultants Ltd.	3171 6823
	Prudential Surveyors International Limited	2507 8333
	CWL Architects & Surveyors Limited	2356 9633
	Building Diagnostic Consultants Limited	2429 8622

New Territories East

District	Consultant	Contact No.
North	Easy Living Consultant Limited	2625 0498
	Prudential Surveyors International Limited	2507 8333
	Geotechnics & Concrete Engineering (H.K.) Ltd.	2365 9123
	Building Diagnostic Consultants Limited	2429 8622
Sai Kung	Modern Testing Consultants Ltd.	3171 6823
	IPS Consultants Limited	3588 1752
	Geotechnics & Concrete Engineering (H.K.) Ltd.	2365 9123
Shatin	Prudential Surveyors International Limited	2507 8333
	Geotechnics & Concrete Engineering (H.K.) Ltd.	2365 9123
	Multiple Surveyors Limited	3966 6766
	Easy Living Consultant Limited	2327 8599
	Property Society International of Architecture Consultant Hong Kong Limited	2363 1894
Tai Po	Easy Living Consultant Limited	2625 0498
	Prudential Surveyors International Limited	2507 8333
	Modern Testing Consultants Ltd.	3171 6823
	Geotechnics & Concrete Engineering (H.K.) Ltd.	2365 9123

New Territories West

District	Consultant	Contact No.
Kwai Tsing	Multiple Surveyors Limited	3966 6766
	Easy Living Consultant Limited	2625 0498
	Building Diagnostic Consultants Limited	2429 8622
Tsuen Wan	Modern Testing Consultants Ltd.	3171 6823
	Prudential Surveyors International Limited	2507 8333
	Building Diagnostic Consultants Limited	2429 8622
Tuen Mun	Modern Testing Consultants Ltd.	3171 6823
	IPS Consultants Limited	3588 1752

	Building Diagnostic Consultants Limited	2429 8622
Yuen Long	Modern Testing Consultants Ltd.	3171 6823
	Prudential Surveyors International Limited	2507 8333
	Building Diagnostic Consultants Limited	2429 8622